

City of Detroit
Department of Recreation Performance Audit
Exhibit 3 – River Rouge Park



Roof on the shelter was badly in need of repair.

City of Detroit
Department of Recreation Performance Audit
Exhibit 3 – River Rouge Park

Comfort Stations

Overall Evaluation – Poor Condition

- The park houses four comfort stations, two were boarded up and one was locked.
- The outside of three of the comfort stations were dilapidated and in need of repair.
- The one open comfort station had deteriorating tile around the stool and urinals as well as dirty floors.



This comfort station was closed and boarded up. Window were broken and the roof needed repair.

City of Detroit
Department of Recreation Performance Audit
Exhibit 3 – River Rouge Park



This comfort station has dirty floors and tiles that were falling from the wall.



Tiles were coming off the wall behind the stool.